





HIETAKARI®




8/25 0TRLM


512/519



# Parts




1. x2




2. 6x30 mm




3. x4



5. x1




6. x1



8. x1


# Tools




A

$\varnothing 6\text{ mm}$   
B


C – Silicone




D




E




F




1







2



3





4



E

5



6

