



HIE TAKARI®






8/25 8CRLM

# VETRO 517/520




517


520



# Parts




1. x3



2. 5x25 mm  
x7




4/83 31RLM



4. x2


8/65 122LM




5. x1



6. x1




7. x1




8. x1

8/45 11RLM




9. x5

8/85 51RLM




10. x1

1/42 H0RLM



11. x1


8/65 482LM




12. x2

4/83 99RLM


# Tools




A




Ø5 mm  
B




C – Silicone  
D – Glue




E




F




G




H




1




I.




II.




III.








2














4








5








6



7




8



12


9

I.



512/513/514/517


II.






520/521

10

I.



II.



III.

